

To continue its program of quality and design improvement, the manufacturer reserves the right to change specifications, de-

## Technical Information

TECHNICAL SERVICE BULLETIN - 1461

TO: ALL GRAVELY OUTLETS

DATE: FEBRUARY 5, 1974

SUBJECT: HARD STARTING IN 10, 12 AND 14 HORSEPOWER

KOHLER ENGINES, K241, K301, AND K321

Enclosed is a reprint of Kohler Service Bulletin No. 100.

We have not received any reported problems with the above engines until the recent cold weather.

Should you have a customer with a starting problem, please check the engine per this Kohler Bulletin.

M. H. Lange, Manager

Customer Service Department

MHL/bh

Attachment