

GRAVELY *Technical* **BULLETIN**



BULLETIN NO. 1081

DATE: July 7, 1964

TO: ALL OUTLETS

SUBJECT: Removal of Flywheel Nut Lockwasher

The two Flywheel Nut Lockwashers (Part Number L-113) have been removed from production models of L-series Tractors and Westchesters.

It has been found that a higher torque value and locking action can be obtained by excluding the Lockwashers from the Flywheel Assembly. The Lockwashers were found to bite their way into the Flywheel, thereby preventing the Flywheel Nut from tightening fully.

##