

BULLETIN NO. 937

DATE:

January 19, 1962

TO:

ALL OUTLETS

SUBJECT:


HOW TO WIRE BOLT HEADS

The sketch with this bulletin shows the proper procedure to use in wiring bolts to prevent loosening from vibration and other causes.

The principle behind such wiring is simply to wire so that the direction of force on the bolt head is always pulling to TIGHTEN the bolt. Careless or incorrect wiring can often increase instead of alleviate the problem.

MISSING TRACTOR

Tractor with Serial Number SR7950, missing in the vicinity of Pollock, La. Customer purchased tractor, made no payments, moved away without leaving a forwarding address. If you know any information about this tractor, please contact Carey Grigg, Credit Manager, or notify Station 39. Missing since approximately April, 1961.



Note position of wire thru the holes tends to tighten the cap screws when tension is put on the wire.

