GRAVELY BULLETIN

BULLETIN NO. 1159

DATE:

APRIL 1, 1965

TO:

ALL OUTLETS

SUBJECT:

IGNITION SWITCH

After present stock is exhausted, we will no longer supply the McGill #73 Ignition Switch.

Replace with the present Ignition Switch being used on the LT Model Tractor. Available May 1, 1965, will be a new style stop button that has the OD of metal and will ground to the handle, requiring only one wire. This stop button will be correct size and ID of handle need not be enlarged. A 1/2" wire exit hole will need to be drilled on older handle. Handles now being supplied from Factory will be drilled to handle this new switch.

Order by part numbers:

1	8244	Switch Button	1.50	
1	8245	Wire	.75 * (Present pl	lastic button requires
1	8265	Grommet	.10	two wires)

###