

PENNINGTON 48" GRAVELY MOWER ATTACHMENT

1962 MODEL 690A - PARTS LIST

PART NO.	DESCRIPTION	QUAN.	LOCATION
H 1913	Deck	1	
H 2161	Reinforcing bars	6	Deck
*	Hex cap screws - 5/16 x 1-1/4	12	Reinf. bars & spdles.
*	Flat washers - 5/16	12	Reinf. bars & spdles.
*	Lock nuts - 5/16	12	Reinf. bars & spdles.
H 306	Safety Guard		Deck - right side
*	Carriage bolt - 1/2 x 1	2	Safety Guard
*	Lock Washers - 1/2	2	Safety Guard
*	Nuts - 1/2	2	Safety Guard
H 310	Runners	2	Deck
*	Carriage bolt - 3/8 x 1-1/4	2	Runners
*	Hex cap screw - 3/8 x 1-1/4	2	Runners
*	Lock washers - 3/8	4	Runners
*	Nuts - 3/8	4	Runners
H 827	Anti-wrap cups	3	Blades
H 207	Blades - 16" <i>Short</i>	3	
H 1910	Belt 5L430	2	Side pulleys
H 1919	Belt 112 BBHD <i>LONG</i>	1	Drive
H 105	Idler Pulley 5"	1	
H 1920	Idler Pulley 7-1/2"	1	
H 1921	Bolt 5/8 x 4	1	Idler Pulley
H 1922	Spacer 5/8 ID	1	Idler Pulley
*	Lock Washer	1	Idler Pulley
H 1923	Nut Weldment	1	Idler Pulley
H 1924	Adjusting Screw Sleeve	1	
H 1925	Adjusting Screw 1/2 x 2	1	
H 1926	Trash Guard and Decal	1	
H 1927	Trash Guard Supports	2	Trash Guard
*	Hex cap screw 5/16 x 3/4	6	Trash Guard
*	Flat Washer 5/16	6	Trash Guard
*	Lock Nuts 5/16	6	Trash Guard
H 1928	Mounting Plate	1	
H 1929	Spec. Shoulder Bolts	4	Mounting Plate
H 1930	Spec. Washers	4	Mounting Plate
*	Hex cap screws 1/2 x 1-1/4	6	Mounting Plate
*	Lock Washers 1/2	6	Mounting Plate
*	Nuts 1/2	6	Mounting Plate
H 1916	Pulley and tapered hub	1	P.T.O.
H 1911	Pulley and tapered hub	2	Side spindles
H 43	Pulley and tapered hub	1	Center spindle

\* Can be obtained locally

PENNINGTON 48" GRAVELY MOWER ATTACHMENT

MODEL 690A - PARTS LIST

PART NO.	DESCRIPTION	QUAN.	LOCATION
H 251A8	Side Spindle Assembly-Right	1	Deck
H 251A9	Side Spindle Assembly-Left	1	Deck
H 251A10	Center Spindle Assembly	1	Deck
H 1931	Housing	2	Center & right spindle
H 1932	Housing	1	Left spindle
H 49	Housing ring - 5000-156	6	All spindles
H 1933	Shaft	1	Center spindle
H 1934	Shaft	2	Side spindles
H 826	Shaft Ring - 5100-66	6	All spindles
H 829	Bearings - 203 KD	6	All spindles
H 828	Grease Seal - 63 x 105	6	All spindles
H 53	Woodruff Key - 1/2 x 1/8	3	All spindles
H 52	Drive collar	3	All spindles
H 23A	Special washer 1/2	3	All spindles
*	Lock washer 1/2	3	All spindles
H 862	Alemite grease fitting	3	All spindles
H 54	Nut - (N. F.) 1/2-20	3	All spindles
H 171A4	Wheel-Fork Assembly	2	
H 4A	Wheel Fork	2	Wheel-fork assembly
H 674	Wheel - 8 x 2.75	2	Wheel-fork assembly
H 931	Axle Bolt	2	Wheel-fork assembly
H 312	Lock nut (N. F.) 5/8	2	Wheel-fork assembly
H 6	Spacer 1/2"	2	Wheel-fork assembly
H 7	Spacer 1"	2	Wheel-fork assembly
H 232	Safety Pin	2	Wheel-fork assembly
H 862	Alemite Grease Fitting	2	Wheel-fork assembly
691A	P. T. O. Assembly	1	
H 1935	Clutch dog	1	P. T. O.
H 1936	Housing	1	P. T. O.
H 1135	Housing Ring (5000-206)	2	P. T. O.
H 1937	Shaft	1	P. T. O.
H 1134	Shaft Ring (5100-98)	2	P. T. O.
H 1137	Bearing 205KD	2	P. T. O.
H 1136	Grease Seals (63-303)	2	P. T. O.
H 1939	Woodruff Key 3/16	1	P. T. O.
H 862	Alemite Grease Fitting	1	P. T. O.
H 312	Lock Nut (N. F.) 5/8	1	P. T. O.

\* Can be obtained locally